

# **QualiMaster**

## Fabric inspection and optimized cutting



#### QUALIMASTER is the BMSvision solution for on-loom, grey and finished fabric inspection.


Installed as a stand alone system or as an extension to the BMS **WeaveMaster** MES system, **QUALIMASTER** offers a powerful fabric inspection solution that allows full quality analysis and fabric classification.

Weaving plants equipped with the WEAVEMASTER production monitoring system can integrate QUALIMASTER's powerful "on-loom" inspection package, thus minimizing the risk for off-quality fabric in the weaving plant and reducing the workload in the grey fabric inspection department.

For finished fabric inspection, dedicated software for optimized mapping and cutting allows to maximize the first quality yield with a minimum of cut operations.


#### **Benefits**

- Reduced off-quality through on-loom inspection
- Real time alarms in case of quality problems
- Customer specific ticket printing
- Full quality reporting
- Monitoring inspector efficiency
- Extreme flexibility through built in report generator
- Interface with ERP systems





A QT touch PC



## **On-loom fabric inspection**

To reduce the risk for off-quality, **QUALIMASTER** offers a solution for "on-loom" inspection. Using BMSvision Data Units installed on the looms, the roving inspector enters the defect code or declares the fabric "defect free". Each entry is automatically related to the pick counter, allowing the generation of a piece map during weaving.

Based on the concentration of defects and stops, the system predicts the quality of the fabric. Alarm messages are generated in case of an off-quality fabric and at doffing, the system formulates a quality advice.

In case of first grade, no further inspection is required and the fabric roll can be transferred to finishing or to the finished goods warehouse. If the calculation shows a risk for off-quality, then the roll is sent to the grey inspection or mending department.

Of course, **QUALIMASTER** also integrates the BMSvision **Cyclops** and **Argus** automatic on-loom inspection system.

## Fabric inspection terminal (QT)

In grey and finished fabric inspection, the inspection frames are equipped with QT touch PCs. Linked with the length counter, ticket tagging device, machine signals, ... the QT offers a user friendly interface for defect entry.

The inspector enters the defect just by tapping the corresponding defect button on the screen. Screen layouts can be configured to meet customer's requirements. A defect map with grade calculation is available on the terminal.

In finished inspection and cutting, instructions can be displayed for cutting and packing the finished goods roll. These instructions can be extracted from the customer related information as stored in the ERP system.


## Piece map and ticket printing

For each piece inspected, be it on-loom, in the grey or in the finished inspection department, **QUALIMASTER** generates and stores a piece map. The piece map consists of a user definable header, a summary graph showing the concentration of defects throughout the piece and a detailed list of all defects with their length and width location.

Through edit functions, the user can add, delete or modify defects, insert notes or change the length of the piece. Piece maps can be exported in PDF, CSV or XML format and can be archived for long time storage if required.

In case bigger rolls are cut into small output pieces, **QUALIMASTER** allows the reconstruction of the input roll starting from an output piece or can show all output pieces generated from a selected input roll.

At the end of each piece or cut-out, **QUALIMASTER** can print a piece ticket. Customer or style dependent ticket layouts can be defined by the user. **QUALIMASTER** translates the inspection results in commercial information such as piece length, grade, allowance, ... which are printed on the final piece ticket.




Piece map with cutouts

#### **Quality reporting**

The **QUALIMASTER** fabric inspection software comes with extensive reporting. By means of the integrated report generator, these reports can be customized to suit the needs of every textile mill.

#### **Typical reports are:**

- Defect analysis by style: to identify the most important defects in a particular style.
- Grade overview by style: to identify critical styles from a quality point of view.
- Inspector performance report by style.
- Quality trend report by style to see the evolution of the quality over a longer time period.



**Alarm handling** 


With the **QUALIMASTER** alarm handling module, the quality manager can follow up on piece quality in real time. Alarm criteria and alarm priorities can be defined for each style or group of styles. Active alarms will appear as a banner in the **QUALIMASTER** reports, are displayed on the inspection terminal and are visible in the piece map. In on-loom inspection, a lamp in the loom's lamp tree can be activated in case of an alarm.

Alarm analysis reports show all the alarms that occurred during a specified period.

Alarm overview

10 2 3 1 2 0	ļļ	Alarms per Style		9 = e + r o	Unh Res Ope War Alar	et 100 n 80 ning 80 m 80	h	Marms: G		Fotal		5 Warn 5 Alarn 7 Critic Cumulat	n al
0 1	Style	Piece	Frame	Alam	Length (m)	E Defects/100m		Wan		Alar Open Time		Crit Open Time	
9111	Como	100/1	2	High Conc	156.0	2.10	4.20	0.03.57		open rine	~	open rate	
		155/1	2	High Conc	77.0					8			
PE		2			233.0		4.09	0.04.12	100.0				
	Lecco	1712/1	1	High Conc Majors	120.0					2.40.30	100.0		100.0
		1		and Comment	120.0	7,50	15.00	E		240:30	11.56		88.4
	Lecco+	155/2	2	High Conc	117.0	3.42	3.42	0.00.11	100.0	101000	1000		100
		1		( Contraction of the second	117.0	3.42	3.42	0.00.11	100.0	1			
	Milano	100/2	2	High Conc Majors	100.0		83.33 83.33		100.0			0:04:08	100.00
		333/1	1	High Conc Majors	55.0 55.0		14.55		100.0			4:04:44	100.00
		203/2	1	High Conc Majors	55.0	3.64						0.00.18	100.0
		1712/2	4	Loding	133.0		0.75		100.0				
-8		4		-	343.0		10.59	0.05.05	200	A	-	4 09 10	98.00

## **Optimized mapping and cutting**



**QUALIMASTER** offers a very powerful package to optimize the cutting of big rolls into smaller pieces.

If inspection and cutting are done in a two-step process, **QUALIMASTER** calculates where to cut the fabric based on the defect map and grading criteria. It takes into account customer requirements such as minimum/maximum piece length, minimum defect free zones, etc. and generates a cut proposal so that a maximum yield in first quality is obtained. These cutting instructions can be printed out or sent directly to a terminal at the cutting table upon identification of the roll.

Interfaces are available for automatic cutting and packing machines. **QUALIMASTER** sends the cutting instructions to the computer of the cutting machine that cuts the roll into smaller pieces as calculated and prints the labels to be fixed to every piece.

		ction Shi	et of		: 561230											6	
Department: Piece: Style: Warp: Order: Calori Leon: Frame: Inspector:		Cytima 56123040 001076 0 3 Hutter		Esc Gr Stu Lat	Start Date: End Date: Grading Table: Standard Width (cm) Length (m) Inspected length (m):		2501.6		Didectr/107mi: 3.28     Pointr/107mi: 74.95     Pointr/107mi: 74.95     Pointr/107mi: 82     Pointr: 82     Pointr: 82     Pointr: 0     Pointr: 0     Defect Length (m): 419.0     Grader: Catoball			Top Defects					
Cato				View	View Output Pieces & Defect Occurrences								Point Concentration				
Nr Fro	1st 0 0	200 o Action 11 SK Tube	400 Let On Length		000 1,00 2nd 3rd ength Length	Off Qual 1)	t Goade Offi		2,000 Out Re Splice free 1	NON A	400 Position 0.0 1.1	and the second	Code	Description	00 1100 1400 1700 Remarks Start Tube End RD: 140.5m RD		
		40.5 S/E Tube				139.6		0.00 CatchAll	Ra-Weekah		11				EndTubeChart Tube	0000100000	
		42.1 StE Tube			94.5	1.6		0.00 CatebAll	Splice free 1		140.5	4.00	-		EndTubeCtart Tube		
		40.6 S/E Tube			94.5	4.0		0.00 Gege 2nd 0.00 CatelsAll	Re-Weakahi Splice free 3		141.0	• 00	822	96256	EndTake Start Take		
4 14						2.2		0.00 CalebAll	Splace free 3 Re. Wookahl		142.1	4.00	300	CME	End RD 236 fon RD	with Of the	
4 14 5 23		4.0 9 6 10 9.4										00	100	COMPLEX.	DIMENT AND DEL RD		
4 14 5 23 6 24	40.6 2	48.3 S/E Tube									226.6				For Take Class Take	sengue se sen	
4 14 5 23 6 24 7 24	40.6 D 48.3 D	SI 5 SE Tube			49.7	3.2	12	5.00 CatebAll	Splice free 1		236.6				EndTubeCtart Tabe	angus re sa	
4 14 5 23 6 24 7 24 8 25	40.6 2 48.3 2 51.5 3	51.5 SOE Tube 01.3 SOE Tube	20.6		49.7		12	5.00 CatebAll 0.00 Gege 2nd			240.6	+.00	309	SMR	EndTubeGtart Tube		
4 14 5 20 6 24 7 24 8 25 9 30	40.6 2 48.3 2 51.5 3 01.2 2	51.5 SOE Tube 01.3 SOE Tube 21.8 Statiliet	20.6		49.7	3.2	12 40	5.00 CatebAll	Splice free l Re-Wookahi	2° -	240.6	4.00	309	3MR	EndTubeCtart Tube End RD: 248 Jas RD		
<ul> <li>4 14</li> <li>5 20</li> <li>6 24</li> <li>7 24</li> <li>8 25</li> <li>9 30</li> <li>10 32</li> </ul>	40.6 2 48.3 2 51.5 3 01.2 3 21.8 3	51.5 SOE Tube 01.3 SOE Tube	20.6		49.7		12 40 40	5.00 CatebAll 0.00 Gage 2ad Short1st 0.00 CatebAll	Splice free I Re-Wookshi Re-Wookshi		240.6	4.00 4.00	- 55.54	court.	EndTubeGtart Tube		
4 14 5 20 6 24 9 20 10 32 11 30	40.6 0 48.3 2 51.5 3 01.2 2 21.8 3 11.6 3	51.5 50E Tube 01.3 50E Tube 21.8 Statilist 01.6 50E Tube	20.6			9.3 9.8	12 40 40 3	5.00 CatebAll 0.00 Gage 2nd ShortLat 0.00 CatebAll 4.78 ShortLat	Splice free l Re-Wookahi	ength	240.6 240.6 248.3		- 55.54	court.	EndTubeCtart Tube End RD: 248 Jas RD		
4 14 5 20 6 24 9 20 10 32 11 30 12 34	40.6 0 48.3 2 51.5 0 01.2 2 21.8 3 11.6 3 43.1 3	51.5 502 Tube 01.2 502 Tube 21.8 Statilat 01.6 502 Tube 43.1 502 Tube	20.6		n.s	9.3 9.8	13 40 40 3 40	5.00 CatebAll 0.00 Gage 2ad Short1st 0.00 CatebAll	Splice free 3 Re-Wookahi Re-Wookahi Splice free 3	le engtik le	240.6 240.6 248.3 250.5		617	PSM.	EndTubeGtart Tube End RD: 248 Jan RD EndTubeGtart Tube	Longth: 7.7m	
4 14 5 20 6 34 7 24 8 25 9 30 10 32 11 30 12 34 13 35	40.6 2 48.3 2 51.5 3 01.2 2 21.8 3 11.6 3 43.1 3 54.1 3	51 5 502 Tube 01 3 502 Tube 21 8 Station 31.6 502 Tube 43.1 502 Tube 54.1 502 Tube	20.6		11.5 11.0	9.3 9.8	13 40 40 3 40	5.00 CatebAll 0.00 Gage 2nd Short1st 0.00 CatebAll 4.78 Short1st 0.00 Gage 2nd	Splice free 3 Re-Wook do Splice free 3 Re-Wook do	engtă Inglă	240.6 240.6 248.3 250.5 251.5	4.00	617	PSM.	EndTubeStart Tube End RD: 248 Jan RD EndTubeStart Tube EndTubeStart Tube	Longth: 7.7m	
4 14 5 20 7 24 9 25 9 30 10 32 11 30 12 34 13 35 14 37	40.6         2           48.3         2           51.5         3           51.5         3           51.5         3           51.5         3           51.5         3           51.5         3           51.5         3           51.6         3           51.7         3           51.8         3           51.6         3           51.7         3           54.1         3           72.2         3	51 5 502 Tube 01 3 502 Tube 21 8 Station 01 6 502 Tube 43 1 502 Tube 54 1 502 Tube 72 2 502 Tube	20.6	266.0	11.5 11.0	9.8 9.8	13 40 40 3 40	5 00 CatchAB 0.00 Guge 2nd ShoetList 0.00 CatchAB 4.78 ShoetList 0.00 Guge 2nd 5.52 ShoetList	Splace free 3 Re-Wookahi Splace free 3 Re-Wookahi Splace free 3	engtă Inglă	240.6 248.3 250.5 251.5 251.5	4.00	617 308	PSM SCL	EndTobeCtart Tobe End SD: 248 Jan RD EndTobeCtart Tobe EndTobeCtart Tobe EndTobeCtart Tobe End RD: 301 Jan RD	Length: 7.7m Length: 49.7m	
4 14 5 20 6 24 7 24 8 25 9 30 10 32 11 30 12 34 13 35 14 37 15 37	40.6         2           48.3         2           51.5         3           01.2         3           01.4         3           01.5         3           01.6         3           01.1         3           03.1         3           04.1         3           72.2         3           79.8         6	51 5 5/8 Tube 51 5 5/8 Tube 21 8 Station 51 6 5/8 Tube 54 1 5/8 Tube 54 1 5/8 Tube 72 2 5/8 Tube 79 8 5/8 Tube			11.5 11.0	9.8 9.8	12 40 40 3 40 40	5 00 CatchAB 0.00 Gugo 2nd ShortLit 0.00 CatchAB 4.78 ShortLit 0.00 Gugo 2nd 5.52 ShortLit 0.00 CatchAB	Splace free 3 Re-Wookahi Splace free 3 Re-Wookahi Splace free 3	engtă Inglă	240.6 248.3 250.5 251.5 251.5 301.2	4.00 4.00	617 308	PSM SCL	EndTubeCtust Tube End RD: 248 Jm RD: EndTubeCtast Tube EndTubeCtast Tube End RD: 301 2m RD End RD: 301 2m RD End TubeCtast Roll	Longth: 7.7m Longth: 49.7m Longth: 9.8m	
4 14 5 22 6 34 9 30 10 32 9 30 10 32 11 30 12 34 13 35 14 37 15 37 16 62 17 92	40.6 2 48.3 2 51.5 3 11.2 3 11.6 3 12.5 3 11.6 3 11.6 3 12.5 3 11.6 3 12.5 3 11.6 3 12.5 3 11.6 3 12.5 3 13.6 3	51 5 5/8 Tube 51 5 5/8 Tube 21 8 Station 51 6 5/8 Tube 51 1 5/8 Tube 54 1 5/8 Tube 54 2 5/8 Tube 79 8 5/8 Tube 25 2 Cool/End	245.4	266.0	11.5 11.0	32 98 76	12 40 3 40 2.52 5.67 5.33	5.00 CatchAll 5.00 Gege 2nd ShortLit 0.00 CatchAll 4.78 ShortLit 0.00 Gege 2nd 5.52 ShortLit 0.00 CatchAll 1st	Splice free k Re-Wookshi Splice free k Re-Wookshi Splice free k Re-Wookshi Splice free k	engtå	240.6 240.6 248.3 250.5 251.5 251.5 301.2 321.8	4.00 4.00	617 308 308	75M SCL SCL	EndTubeStart Tube End RD: 248 Jm RD EndTubeStart Tube EndTubeStart Tube End RD: 301 Jm RD End RD: 301 Jm RD End RD: 331 6m RD	Langth: 7.7m Langth: 49.7m Langth: 9.8m	

Through interfaces with automatic palletizers, the pieces that are cut and packed are automatically put on the right pallet. **QUALIMASTER** knows when the pallet or container is completed and gives the instructions to transport it to the finished goods warehouse.

#### Benefits

- Increased output of first grade fabric.
- Reduced customer complaints.
- Grading criteria per style/customer.
- Interface with automatic cutting and packing machines.

Cut instruction sheet



#### BMSvision

sales@bmsvision.com www.bmsvision.com Belgium: +32 56 262 611 United Kingdom: +44 1254 662 244